




Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	$L \begin{smallmatrix} -0,10 \\ -0,30 \end{smallmatrix}$
30	40	60
31,5	42	30
		40
32	42	20
		30
		40
35	44	20
		25
		30
		35
		40
		45
		50
		60
35	45	20
		25
		30
		35
		40
		45
		50
		60
38	48	30
		40
40	50	15
		20
		25
		30
		35
		40
		45
		50
		60
		70
		80
40	55	15
		25
		30
		35
		40
		45
		50
		60
45	55	30
		35
		40
		45
		50

Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	$L \begin{smallmatrix} -0,10 \\ -0,30 \end{smallmatrix}$
45	55	60
45	56	30
		35
		40
		45
		50
		60
		70
		80
45	60	30
		35
		40
		45
		50
		60
		70
		80
50	60	20
		30
		35
		40
		45
		50
		60
		70
50	62	30
		35
		40
		45
		50
		60
		70
50	65	30
		40
		45
		50
		60
		70
		80
		100
55	70	30
		35
		40
		45
		50
		60
		70

Dimensioni (mm) Dimensions (mm)		
$d_{(F7)}$	$D_{(m6)}$	$L \begin{smallmatrix} -0,10 \\ -0,30 \end{smallmatrix}$
60	74	30
		35
		40
		45
		50
		60
		70
		80
60	75	30
		35
		40
		45
		50
		60
		70
		80
		100
63	75	50
		60
		70
63	76	60
		70
		80
65	80	40
		50
		60
		70
		80
70	85	30
		35
		40
		45
		50
		60
		70
		80
		100
70	90	50
		60
		70
		80
75	90	50
		60
		70
		80
		100
75	95	60